


18 E Franklin St.




18 E Franklin.  
Downspout issues.  
2-28-24

18 E Franklin St.



Newer WH. 2-28-24.  
18 E Franklin


18 E Franklin St.



18 E Franklin. 2-28-24.  
Rear of home

18 E Franklin St.

Downspout issues.  
18 E Franklin.  
2-28-24



18 E Franklin St.



18 E Franklin.  
Dining room floor  
settling. 2-28-24


18 E Franklin St.



18 E Franklin.  
2-28-24.

18 E Franklin St.

Crawl area under  
home. 18 E Franklin.  
2-28-24



18 E Franklin St.



Floor settling.  
18 E Franklin.  
2-28-24




18 E Franklin St.



Floor settling. 18 E Franklin.  
2-28-24


18 E Franklin St.




18 E Franklin.  
Newer HVAC.  
2-28-24

18 E Franklin St.

18 E Franklin.  
Front LR. 2-28-24.  
Floor settling.




18 E Franklin St.



Sump pump needs  
replaced. 18 E Franklin.  
2-28-24

18 E Franklin St.



18 E Franklin. 10-18-24.  
Floor sinking

78 Adams Ave.

78 Adams. Siding & soffit issues.  
10-18-24




78 Adams Ave.



78 Adams.  
Damaged soffits.  
10-18-24

78 Adams Ave.



Damaged siding. 78 Adams.  
10-18-24



78 Adams Ave.



78 Adams. 10-18-24.  
Siding.

78 Adams Ave.



Bad siding/paint. 78 Adams.  
10-18-24

78 Adams Ave.



Front porch ceiling.  
78 Adams. 10-18-24

78 Adams Ave.

**78 Adams. 10-18-24.  
Damaged soffits.**




78 Adams Ave.



Damaged siding. 10-18-24.  
78 Adams

78 Adams Ave.




78 Adams. Siding etc. 10-18-24

78 Adams Ave.

78 Adams. 10-18-24 Siding




78 Adams Ave.



78 Adams. Bad siding.  
10-18-24




78 Adams Ave.




78 Adams. 10-18-24. Siding.

78 Adams Ave.




78 Adams. Siding & downspouts.  
10-18-24

78 Adams Ave.



78 Adams. Siding. 10-18-24

78 Adams Ave.



78 Adams. Dilapidated siding.  
10-18-24



78 Adams Ave.



78 Adams. 10-18-24.  
Siding.

225 S. Bosse Ave.



Siding installed incorrectly.  
10-18-24. 225 S Bosse

225 S. Bosse Ave.

225 S Bosse.  
Missing gutters.  
10-18-24





225 S. Bosse Ave.

225 S Bosse.  
10-18-24



225 S. Bosse Ave.



Steps rotted. 225 S Bosse.  
10-18-24

225 S. Bosse Ave.




Steps rotted. 225 S Bosse.  
10-18-24

225 S. Bosse Ave.

Missing & failing soffit.  
10-18-24. 225 S Bosse




225 S. Bosse Ave.



Siding installed  
incorrectly. 10-18-24.  
225 S Bosse

225 S. Bosse Ave.

Missing gutters. 225 S Bosse.  
10-18-24



1112 S. Bennighof

1112 S Benninghof.  
Roof damaged.  
10-15-24



1112 S. Bennighof



1112 Bennighof. 10-15-24.  
Roof damaged




1112 S. Bennighof



1112 Benninghof.  
10-15-24. Roof  
bad

1331 Gavitt St.

1331 Gavitt St.  
loose outlets.  
10-15-24




1331 Gavitt St.



1331 Gavitt. Side yard. 10-15-24

1331 Gavitt St.

Loose handrail.  
1331 Gavitt.  
10-15-24



1331 Gavitt St.



1331 Gavitt. 10-15-24

5301 Chadwick Rd.

5301 Chadwick.  
7-1-24




5301 Chadwick Rd.

5301 Chadwick.  
Bath walls.  
10-15-24



5301 Chadwick Rd.

5301 Chadwick. 10-15-24.  
Missing bath walls






5301 Chadwick Rd.




Exterior bathroom window.  
5301 Chadwick. 10-15-24

5301 Chadwick Rd.



5301 Chadwick. 10-15-24.  
West side window

5301 Chadwick Rd.



5301 Chadwick.  
Bad shower/tub.  
10-15-24

5301 Chadwick Rd.

5301 Chadwick.  
Bath walls.  
10-15-24




5301 Chadwick Rd.

5301 Chadwick.  
Bathroom. 10-15-24



5301 Chadwick Rd.

Bad wall in hall.  
5301 Chadwick.  
10-15-24



5301 Chadwick Rd.



5301 Chadwick Rd.

Damaged kitchen cabinets.  
5301 Chadwick. 10-15-24





5301 Chadwick Rd.

5301 Chadwick. 10-15-24.  
Kitchen damage



5301 Chadwick Rd.

5301 Chadwick.  
10-15-24.  
Dilapidated bathroom



5301 Chadwick Rd.

